**Difference with the best lap**
Previous lap number

Previous lap time

④ To end measurement, press and hold the LAP button.

To restart the measurement

Press the LAP button again. The stopwatch restarts measuring.
▶ Measurement starts from the next lap.

To Check or Clear the Lap Time

Select the "LAP TIME" menu in the setting mode.

Operation Guide