

7. Warm up the engine at 2,000–2,500 min^{-1} (2,000–2,500 rpm) until it runs smoothly with the choke open. (B)

NOTE: When the temperature is extremely low, prime the engine before starting by cranking several times with the kickstarter. The ignition switch should be turned OFF. Keep the choke closed and the throttle opened.

7. Caliente el motor haciéndolo marchar en vacío a 2.000–2.500 min^{-1} (2.000–2.500 rpm) hasta que corra suavemente, con el estrangulador abierto (B).

NOTA: Cuando la temperatura es extremadamente baja, cebar el motor, antes del arranque, dano manivelas al motor varias veces con el arranque de pie. En ese momento, el interruptor del encendido deberá estar colocado en posición OFF. Mantenga el estrangulador cerrado y el acelerador abierto.