


Temperature Gauge

When the needle (1) begins to move above the C (cold) mark (2), the engine is warm enough to operate. The normal operating temperature range is within the zone between the C and H marks. If the needle reaches the H (Hot) mark, stop the engine and check the reserve tank coolant level. Read pages 120-124 and do not ride the motorcycle until the problem has been corrected.

NOTE: Exceeding maximum running temperature may cause serious engine damage.



Indicador de temperatura

Cuando la aguja (1) comience a moverse sobre la marca C (frío) (2), el motor estará lo suficientemente caliente como para funcionar. La gama de temperatura de funcionamiento normal está entre las marcas C y H. Si la aguja alcanza la marca H (caliente), parar el motor y comprobar el nivel de refrigerante en el depósito de reserva. Lea las páginas 120 a 124 y no conduzca la motocicleta hasta después de haber corregido el problema.

NOTA: El motor podría dañarse seriamente si se sobrepasase la temperatura de funcionamiento máxima.