


3. Check for correct synchronization of the oil pump (3). Check the reference mark (4) aligns with the index mark (5) with the throttle fully opened. See your authorized Honda dealer if any misalignment occurs.

**CAUTION :**

- **Failure to perform oil pump synchronization may result in serious engine damage.**



- (3) Oil pump  
(4) Reference mark  
(5) Index mark