


WIRING DIAGRAM



B	BLACK	B	BROWN
V	VIOLET	D	DIAMOND GREEN
Bl	BLUE	L	LIGHT BLUE
G	GREEN	SP	SPARK GREEN
R	RED	P	PINK
W	WHITE	Gr	GRAY

0030Z - HMs - 0000

STARTER SWITCH	STARTER BT		
	PRES	PUSH	ON
	COND	COND	IN
	COND	COND	IN

ENGINE STOP SWITCH	START	STOP	STOP
	OFF	OFF	OFF
	NUM	NUM	NUM
	OFF	OFF	OFF
	COND	COND	COND
	COND	COND	COND

IGNITION SWITCH	IGNITION	IGNITION	IGNITION	IGNITION	IGNITION	IGNITION	IGNITION
	OFF	ON	ON	ON	ON	ON	ON
	COND	COND	COND	COND	COND	COND	COND
	COND	COND	COND	COND	COND	COND	COND

IGNITION SWITCH	IGNITION	IGNITION	IGNITION	IGNITION	IGNITION	IGNITION	IGNITION
	OFF	ON	ON	ON	ON	ON	ON
	COND	COND	COND	COND	COND	COND	COND
	COND	COND	COND	COND	COND	COND	COND