


WIRING DIAGRAM



- BI BLACK
- Y YELLOW
- Bu BLUE
- G GREEN
- R RED
- W WHITE
- B BROWN
- O ORANGE
- L3 LIGHT BLUE
- L4 LIGHT GREEN
- P PINK
- Gr GRAY

0030Z-HN1-0000

STARTER SWITCH

BAT2	IG	ST
FREE		
PUSH		
COLOR	BI	Y/R

SPARK STOP SWITCH

BAT2	IG
OFF	
RUN	
OFF	
COLOR	G / Bu/W

SWITCH CONTINUED

H	HL	Lo
H		
COLOR	Bu	W

LIGHTING SWITCH

BAT2	TL
OFF	
ON	
COLOR	BI

IGNITION SWITCH

IG	E	BAT	HQ
OFF			
ON			
COLOR	Bu/Y	G	R