
Changing down the gears

Changing down gears provides greater acceleration in situation such as overtaking. Avoid changing down at high speed, which can damage both the engine and the transmission by running the engine at excessively high rpm. The table shows the maximum speed for each shift down.

	Maximum Speed
5th - 4th	130 km/h
4th - 3rd	100 km/h
3rd - 2nd	70 km/h
2nd - 1st	45 km/h