

Checking the Drive Chain Wear

If the drive chain slack is excessive when the rear axle is moved to the furthest limit of adjustment, the drive chain is worn and must be replaced.

Chain:

HUZHOU SHUANSHI 428H
KMC 428HDF

If necessary have the drive chain replaced by your dealer.