

## Appearance Care

---

The headlights' inside lens may fog temporarily after washing or while riding in the rain. This does not impact the headlight function.

Any condensation inside the headlight should dissipate after a few minutes of running the engine with the headlights on.

However, if you see a large amount of water or ice accumulated inside the lenses, have your vehicle inspected by your dealer.