

Radiator Servicing

The cooling system should be serviced every 6 months or every 10,000 km (6,000 miles), and changed every 2 years or every 40,000 km (24,000 miles).

Recommended coolant:

Use only a high quality ethylene glycol base anti-freeze containing inhibitors for corrosion protection and specifically recommended for use in aluminum engines. The GL1000 cooling system has a 50/50 solution of anti-freeze and water from the factory.

Limpieza del radiador

El sistema de enfriamiento deberá limpiarse cada 6 meses de servicio o cada 10.000 km de recorrido, y deberá reemplazarse por uno nuevo cada dos años o cada 40.000 km de recorrido.

Líquido de refrigeración recomendado:

Utilice sólo una solución anticogelante de base de etilenglicol de buena calidad que contiene inhibidores para la protección contra corrosión y las recomendadas específicamente para el uso para motores de aluminio. El sistema de enfriamiento del GL1000 tiene una solución 50/50 de anticongelante y agua, ya llenada en la fábrica.