

(Ref.No.) Description	Function
(9) High beam indicator (blue)	Lights when the headlight is on high beam.
(10) Odometer/Tripmeter select and reset button	This button is used to reset the tripmeter or to select the tripmeter or odometer (page 15).