

## Gauges, Indicators & Displays

---

7	multi-function display	The display includes the following functions: <i>Display Check.</i>
	speedometer	Shows riding speed in miles or kilometers per hour (page 21 ).
	tachometer	Shows engine speed in revolutions per minute (rpm) (page 21 ).
	tachometer red zone	Shows excessive engine rpm range (indicated from the beginning of the tachometer red zone) in which operation may damage the engine. Do not let the tachometer rpm display enter the red zone.
	odometer	Shows the total miles or kilometers ridden (page 22 ).
	tripmeter A & B	Shows the number of miles or kilometers ridden since you last reset the meter. The tripmeter has two sub modes, "A" and "B." To zero (0) the tripmeter, push and hold the reset switch for more than 2 seconds (page 23 ).
	digital clock	Shows hour and minute (page 25 ).