

BATTERY

(Refer to the maintenance precautions on page 47).


If the motorcycle is operated with insufficient battery electrolyte, sulfation and battery plate damage will occur.

If rapid loss of electrolyte is experienced, or if your battery seems to be weak, causing electrical problems, see your authorized Honda dealer.

Battery electrolyte:

The electrolyte level must be maintained between the UPPER (1) and LOWER (2) LEVEL marks on the side of the battery. If the electrolyte level is low, remove the battery filler caps on top of the battery.

Carefully add distilled water to the UPPER LEVEL mark using a small plastic funnel.



- (1) UPPER LEVEL mark
- (2) LOWER LEVEL mark