




WIRING DIAGRAM



- Br Brown
- Bk Black
- W White
- R Red
- Y Yellow
- B Blue
- G Green

ENGINE STOP SWITCH CONTINUITY

| | | |
|-------|----|---|
| | IG | E |
| OFF | | |
| ON | ○ | ○ |
| COLOR | Bk | G |

LIGHTING SWITCH CONTINUITY

| | | | | | |
|-------|-------|---|----|----|----|
| Nob.B | Nob.A | C | TL | Hi | Lo |
| OFF | | | | | |
| ON | Hi | ○ | ○ | ○ | ○ |
| | (N) | ○ | ○ | ○ | ○ |
| | Lo | ○ | ○ | ○ | ○ |
| COLOR | | Y | Bk | B | W |

0030Z—961—0000