


18. WIRING DIAGRAM

WIRING DIAGRAM

'85



0030Z-HA0-000