


# WIRING DIAGRAM

After '85



- Bl ..... Black
- Y ..... Yellow
- Bu ..... Blue
- G ..... Green
- R ..... Red
- W ..... White
- Br ..... Brown
- O ..... Orange
- Lb ..... Light Blue
- Lg ..... Light Green
- P ..... Pink
- Gr ..... Grey

## SWITCH CONTINUITY

IG	E	BAT	H0
OFF	○	○	○
ON	○	○	○
COLOR	B/W	G	R

TL	C	L0	H1
OFF	○	○	○
L0	○	○	○
(N)	○	○	○
H1	○	○	○
COLOR	B	Bi	W

BAT	ST
PUSH	○
FREE	○
COLOR	Bi

E	IG
RUN	○
OFF	○
COLOR	G

0030Z-HA6-6800