


WIRING DIAGRAM



- BI Black
- Y Yellow
- Bu Blue
- G Green
- R Red
- W White
- Br Brown
- O Orange
- Lb Light Blue
- Lg Light Green
- P Pink
- Gr Grey

ENGINE STOP SWITCH

IG	E
OFF	ON
RUN	STOP
COLOR	BI/W G

DIMMER SWITCH

TL	HI	LO
HI	(N)	LO
COLOR	Br	Bu W

SWITCH CONTINUITY

C	TL
OFF	ON
COLOR	W/Y Br

0030 Z - HA 5^A - 0100